

Inspection Report

Company Name LB of Hounslow	Scheduled Start Date 01/05/2025	Inspection Completed on 01/05/2025
Location of Inspection South Bedfont (ESTSBED)	Scheduled Time of Inspection 8:17 AM	Inspection Submission Time 8:22 AM
Inspector that undertook inspection Keith Asuncion	Template Used Estate Inspection	PDF Sent to keith.asuncion@hounslow.gov.uk

Inspection Score and Overall Grade		
Actual Score	Max Score	Inspection %
8	8	100
Banding Name Default Banding	Overall Inspection Result Default Banding Item	

1 Inspection Details		
1.1 - Question Type of Inspection	1.1 - Responses 6 Monthly	
1.2 - Question Area	1.2 - Responses West	
1.3 - Question How many blocks are you inspecting in the estate today?	1.3 - Responses 0	1.3 - Comments 01/05/2025 No blocks or estate, street properties. 1.3 - Comments 01/05/2025 No Caretaking or Grounds Maintenance Service.

17 Overall Estate Rating		
17.4 - Question Please rate the overall Communal Issues of the estate	17.4 - Responses A	
17.5 - Question Please rate the overall Fire Risks of the estate	17.5 - Responses A	17.5 - Comments 01/05/2025 No blocks, street properties.